


karimás gömbcsap szürkeöntvényből sorozat BA040



kialakítás	kétállású golyósszelep hozzá lebegő golyó, teljes átömlési keresztmetszetben nyitható
működtetés	a kézika 90°-os elfordításával
csatlakozás	karima DN25...DN200 EN1092-1 szerint, PN16
hossz	DN25...DN150 EN558-1R14 szerint, DN200 EN558-1R27 szerint
anyagok	öntöttvas ház, gömbtest AISI 304, golyóselem tömítés PTFE, szártömítés PTFE/NBR, acél kézika műanyag borítással
alkalmazás	Az 1-es és 2-es csoport folyadékok és gázai, melyek a felhasznált anyagokra a 2014/68/EU szerint nem ártalmasak. Gőz-alkalmazások esetén speciális golyósszelep használatát javasoljuk.
közeghőmérséklet	-10...+120°C, FKM o-gyűrűvel értékig +160°C
üzemi nyomás	vákuum max. 10^{-3} Torr értékig névleges nyomás a táblázat és a nyomás-hőmérséklet diagramm szerint
Rögzítés módja	beépítés merev sűrített levegő hálózatba
beépítési helyzet	bármelyik
egyedi kivitel	FKM O-gyűrű, antisztatikus kivitel ATEX II 2 D/G c T3

*egyedi kivitel Igény szerint

The graph illustrates the pressure-temperature (P-T) limits for PTFE grades. The y-axis represents pressure in bar (0 to 150), and the x-axis represents temperature in °C (-20 to 180). The curves for different PN grades are as follows:

- PN 140:** Maximum pressure of ~140 bar at 0 °C, stable until ~30 °C, then decreases to 0 bar at 160 °C.
- PN 105:** Maximum pressure of ~105 bar at 0 °C, stable until ~40 °C, then decreases to 0 bar at 160 °C.
- PN 64:** Maximum pressure of ~64 bar at 0 °C, stable until ~55 °C, then decreases to 0 bar at 160 °C.
- PN 42:** Maximum pressure of ~42 bar at 0 °C, stable until ~90 °C, then decreases to 0 bar at 160 °C.
- PN 30:** Maximum pressure of ~30 bar at 0 °C, stable until ~90 °C, then decreases to 0 bar at 160 °C.
- PN 25:** Maximum pressure of ~25 bar at 0 °C, stable until ~90 °C, then decreases to 0 bar at 160 °C.
- PN 16:** Maximum pressure of ~16 bar at 0 °C, stable until ~90 °C, then decreases to 0 bar at 160 °C.
- PN 10:** Maximum pressure of ~10 bar at 0 °C, stable until ~90 °C, then decreases to 0 bar at 160 °C.
- PN 6:** Maximum pressure of ~6 bar at 0 °C, stable until ~90 °C, then decreases to 0 bar at 160 °C.

BA04025L-HU-2019/06 © STASTO Automation KG