


Pneumatic visual indicator Type PC008



Function	The pneumatic visual indicator is used for the visual indication of pressure signals.
Connection	Male thread G1/4", Thread for panel mounting M22x1
Materials	Body Nickel-plated brass
Medium	50µm filtered and lubricated or non-lubricated compressed air
Operating temperature	-5...+60°C
Operating pressure	1,2...10bar



Indicator color	Weight [approx. kg]	Type
red	-	PC008-RD
green	-	PC008-GN

Illustrations non-binding
Design, dimensional and material changes reserved

Pneumatics / Way-valves - mechanically / manually, logic units / Pneumatic timers and automatic valves / Pneumatic indicator Series PC008

